

Off Factor

Voltage


# Ohm's Law

- $V = I \times R$
- $V =$  Voltage
- $I =$  Current measured in Amps
- $R =$  Resistance measured in Ohms
  
- Also  $R = V/I$
- Also  $I = V/R$

# Voltage



# Your Magical Voltage Number = 3.3v




\* Most sensors also run at 3.3v


Don't let out the magic smoke



# Resistor



# Resistor







1st Digit    2nd Digit    Multiplier    Tolerance

→ Gold=5%  
Silver=10%  
None=20%

Black	Black	0	0	x1
Brown	Brown	1	1	x10
Red	Red	2	2	x100
Orange	Orange	3	3	x1,000
Yellow	Yellow	4	4	x10,000
Green	Green	5	5	x100,000
Blue	Blue	6	6	x1,000,000
Violet	Violet	7	7	x10,000,000
Gray	Gray	8	8	x100,000,000
White	White	9	9	-

Thread has resistance  
but not that much




Resistance: 28 Ohms/ft

# Voltage and Resistance are important for:

- Not blowing out your board or components
- Making all LEDs have the same brightness
- Battery life
- Sensors

Attaching

# Soldering



**Do:** Touch the iron to the component leg and metal ring at the same time.



**Do:** While continuing to hold the iron in contact with the leg and metal ring, feed solder into the joint.



**Don't:** Glob the solder straight onto the iron and try to apply the solder with the iron.



**Do:** Use a sponge to clean your iron whenever black oxidation builds up on the tip.



**A** Solder flows around the leg and fills the hole - forming a volcano-shaped mound of solder.



**B** Error: Solder balls up on the leg, not connecting the leg to the metal ring.  
Solution: Add flux, then touch up with iron.




**C** Error: Bad Connection (i.e. it doesn't look like a volcano)  
Solution: Flux then add solder.



**D** Error: Bad Connection...and ugly...oh so ugly.  
Solution: Flux then add solder.




**E** Error: Too much solder connecting adjacent legs (aka a solder jumper).  
Solution: Wick off excess solder.



Sewing







Handwritten text, possibly a date or initials, located in the upper right corner of the page.



Don't cross your thread (or wire)!

## Other methods – but remember your off value

- Hot glue – great insulator
- Snaps – are conductive!
- Iron on adhesive (just remember the adhesive itself may not be conductive)
- Velcro – excellent for larger items like battery packs – conductive Velcro exists
- Buttoneer – great for EL wire
- JST or Ethernet connectors
- Electrical tape – eventually falls off and gums things up (not recommended)